## Date: 20.05.2025

	1.42	2.42	2.54	3.63		3.67			4.71					5.75						5.85			5.87z
	B1E	B2.1	B2.1	B2.1	B3	B4	B6	B3	B6	B09	B3	B6	B09	B9	B011	B11	B3	B6	B09	B9	B011	B11	B10
2D	+	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
65	-	+	+	+	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
8SX	-	+	+	+	+	+	Х	х	х	-	-	-	-	-	-	-	-	-	-	-	-	-	-
8D	-	-	-	-	+	-	+	+	+	-	Х	х	-	х	-	-	Х	Х	-	х	-		x
8DWD	-	-	-	-	+	-	+	+	+	-	х	х	-	х	-	-	х	х	-	х	-		x
9SC	-	-	-	-	+	+	+	+	+	-	+	+	-	х	-	-	+	+	-	х	-	-	-
10D	-	-	-	-	+	-	+	+	+	-	+	+	-	+	-	-	+	+	-	+	-	-	+
10DWD	-	-	-	-	+	-	+	+	+	-	+	+	-	+	-	-	+	+	-	+	-	-	+
12D	-	-	-	-	х	-	-	+	+	-	+	+	-	+	-	-	+	+	-	+	-	-	+
12DWD	-	-	-	-	х	-	-	+	+	-	+	+	-	+	-	-	+	+	-	+	-	-	+
14D	-	-	-	-	-	-	-	х	+	-	х	+	-	+	-	-	х	+	-	+	-	-	+
14DWD	-	-	-	-	-	-	-	х	+	-	х	+	-	+	-	-	х	+	-	+	-	-	+
10U	-	-	-	-	-	-	-	+	+	-	+	+	-	+	-	+	+	+	-	+	-	+	+
10UWD	-	-	-	-	-	-	-	+	+	-	+	+	-	+	-	+	+	+	-	+	-	+	+
11UX	-	-	-	-	-	-	-	+	+	-	+	+	-	+	-	-	+	+	-	+	-	-	+
11UXWD	-	-	-	-	-	-	-	+	+	-	+	+	-	+	-	-	+	+	-	+	-	-	+
12U	-	-	-	-	-	-	-	х	+	-	х	+	-	+	-	+	х	+	-	+	-	+	+
12UWD	-	-	-	-	-	-	-	х	+	-	х	+	-	+	-	+	х	+	-	+	-	+	+
12UAWD	-	-	-	-	-	-	-	х	+	-	х	+	-	+	-	+	х	+	-	+	-	+	+
15U	-	-	-	-	-	-	-	-	-	-	-	+	-	+	-	+	-	+	-	+	-	+	+
15UWD	-	-	-	-	-	-	-	-	-	-	-	+	-	+	-	+	-	+	-	+	-	+	+
15UAWD	-	-	-	-	-	-	-	-	-	-	-	+	-	+	-	+	-	+	-	+	-	+	+
MWD 3.2	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
HMWD 3.2	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-

Marking	Description
+	Available
x	Compatible, but not recommended
-	Not compatible

Additional comments on compatible combinations
Safety grill must be moved backwards to use B11 support leg tilting function.
Execution: B40 + 95C combination is not compatible if T2 tank is mounted to safe

Exception: B4e + 9SC combination is not compatible if T2 tank is mounted to safety grill.

Exception: 8SX+T2 tank is not compatible with B4e support legs.

## Additional comments on compatible, but not recommended combinations

B6.1 support legs are disproportionately large for 8SX trailer. B3 and B4e provide sufficient stability for 8SX + 3.67 combo and therefore make B6.1 not cost effective for 8SX t

3.67 is not designed for higher work capacities that are usual for working with 12D trailer. B6.1 support leg has too low base for 3.67+12D combo.

B9 support legs are disproportionately large for 9SC trailer. Smaller legs provide sufficient support.

B3 support legs may lack reach with bigger trailers when working on uneven terrain.

Heavier 7<sup>th</sup> series cranes would make up significant part of smaller D-series trailers load capacity and will therefore remarkably reduce useful load capacity.

8SX is compatible with 4.71, but not suitable for full-time or heavy use.

8D compatible only with 195 bar versions of 5.75 and 5.85

P	F	M	5

ailer.	

		7.78		7.87						7.94		X100				
	B09	B9	B011	B11	B09	B9	B011	B11	B09	B9	B011	B11	B09.1	B9.1	B011.1	B11.1
65	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
8SX	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
8D	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
8DWD	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
9SC	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
10D	-	+	-	-	-	+	-	-	-	х	-	-	-	-	-	-
10DWD	-	+	-	-	-	+	-	-	-	х	-	-	-	-	-	-
12D	-	+	-	-	-	+	-	-	-	+	-	-	-	-	-	-
12DWD	-	+	-	-	-	+	-	-	-	+	-	-	-	-	-	-
14D	-	+	-	-	-	+	-	-	-	+	-	-	-	+	-	-
14DWD	-	+	-	-	-	+	-	-	-	+	-	-	-	+	-	-
100	-	+	-	+	-	+	-	+	-	+	-	+	-	-	-	-
10UWD	-	+	-	+	-	+	-	+	-	+	-	+	-	-	-	-
11UX	-	+	-	-	-	+	-	-	-	+	-	-	-	-	-	-
11UXWD	-	+	-	-	-	+	-	-	-	+	-	-	-	-	-	-
120	-	+	-	+	-	+	-	+	-	+	-	+	-	+	-	+
12UWD	-	+	-	+	-	+	-	+	-	+	-	+	-	+	-	+
12UAWD	-	+	-	+	-	+	-	+	-	+	-	+	-	+	-	+
15U	-	+	-	+	-	+	-	+	-	+	-	+	-	+	-	+
15UWD	-	+	-	+	-	+	-	+	-	+	-	+	-	+	-	+
15UAWD	-	+	-	+	-	+	-	+	-	+	-	+	-	+	-	+
MWD 3.2	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+
HMWD 3.2	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+

Additional comments on compatible combinations 10U and 10UWD not compatible with 240 bar versions of 7<sup>th</sup> series cranes.

PALMS